

R23 + R24 should not be mounted along with the onboard RFID reader

